



5

3M[™] Speedglas[™] Welding Helmet G5-03

Versatility to upgrade your performance

3M Science. Applied to life.™





3M[™] Speedglas[™] Welding Helmet G5-03 E

G5-03 E Helmet without welding filter Part No 63 10 00

G5-03 E Helmet with welding filter G5-01/03NC Part No 63 10 10

Getting too close to your arc?

Start with the easiest solution first: replace your welding filter's outer protection plates more frequently!

If you can't see the detail you need, try one of our magnifying lenses. They come in x1.0, x1,5, x2.0, x2,5 and x3.0 strengths. For details, see the Accessories and Spare Parts section for each helmet.






The 3M[™] Speedglas[™] Welding Helmet G5-03 E uses multiple parts and components from our other welding helmets.


Accessories G5-03 E 16 91 00 • 16 90 01 16 90 05 16 40 05

Spare parts and consumables G5-03 E



	9	16 91 00			
		16 92 05 •	Hood black/grey Protection plate for task light,	60 10 00 • 63 10 95	Battery holder Helmet shell G5-03 E,
	assive welding filter lens shade		pkg. of 5		no headband
		16 92 15	Task light kit (light, cable, holder		Battery CR2450
	assive welding filter lens shade (90×110)	16 92 16	with cable & battery) Welding Helmet Task Light holder	010011	Speedglas passive welding filter kit G5-01/03 (shade 11)
11 00 13 • Pas	assive welding filter lens shade	16 92 17 •	for battery with attachment parts	61 00 21 •	Speedglas welding filter G5-01/03TW
		42 20 00	Battery CR2032 Lithium 3V, pkg of 2	61 00 31 •	Speedglas welding filter G5-01/03VC
17 10 21 • Ma	agnifying lens 1.5X	52 60 00 •	Outer protection plate (standard),	61 05 01 •	Front frame G5-01/03
	agnifying lens 2.0X		pkg of 10	63 00 10 •	Speedglas welding filter
	o , o	52 70 00 •	Outer protection plate (scratch),		G5-03NC
	agnifying lens 3.0X		pkg of 10	70 50 20	Headband with assembly parts
		52 70 01 •	Outer protection plate (scratch +),	70.00.00	and sweatband
• •	parts) veatband, towelling, purple,	50 70 70 0	pkg of 10	70 60 30	Assembly parts (pivots) for
	g of 2	527070 •	Outer protection plate (heat), pkg of 10	73 10 00	headband Battery holder
	-	52 80 15	Inner protection plate, pkg of 5	ACK081B	Rechargeable Battery
			Inner cover plate, pkg of 5	AL2AI/SP	Battery Charging cable for
16 80 10 Sw			Inner protection plate anti-fog		ACK081B
(ler	enght 24 cm), pkg of 2	52 80 29	Inner protection plate anti-fog,		
16 80 12 Sw	weatband in fleecy cotton		pkg of 5		
		53 62 10 🔹	Cushion part for headband		
	eck protection		G5-01/03		
16 90 05 He	ead protection in fabric	53 62 11 •	Large head rest		





The right equipment for each job



3M[™] Speedglas[™] Welding Helmet G5-01

Heavy duty welding and grinding

3M[™] Speedglas[™] Welding Helmet G5-02

Tig welding

Welding and grinding



Learn more about the G5-03 helmet Scan this QR-code or go to youtube.com/3MSpeedglas

A WARNING

Product standards determine what type and level of protection is provided. Check the technical information and product markings to determine the product standard. This information should be considered but not in isolation when consulting your risk assessment. Always consider local regulation and requirements. The result of the risk assessment should determine if the PPE is an appropriate control. For more information see the user instructions or contact 3M for technical support.



(f) facebook.com/3MSpeedglas



(데) Instagram.com/3MSpeedglas

(m) youtube.com/3MSpeedglas



3M Welding Centre of Excellence SE-78521 Gagnef, Sweden

www.speedglas.com www.3M.com

Please recycle. Printed in Sweden. © 3M 2024. All rights reserved. 3M and Speedglas are trademarks of 3M Company, used under license in Canada. The Bluetooth name and logo are trademarks of the Bluetooth Special Interest Group.